

Denial-of-Service Vulnerability in Ethernet Port of MELSEC and MELIPC Series

Release date: June 14, 2022
Last update date: May 30, 2024
Mitsubishi Electric Corporation

Overview

Denial of Service(DoS) vulnerability due to improper resource locking (failure to release resources) exists in MELSEC iQ-R/Q/L series CPU module and MELIPC series. A malicious attacker may cause a DoS condition in Ethernet communications by sending a specially crafted packet (CVE-2022-24946).

The product models and versions affected by this vulnerability are listed below.

CVSS¹

CVE-2022-24946 CVSS:3.1/AV:N/AC:L/PR:N/UI:N/S:U/C:N/I:N/A:H Base Score:7.5

Affected products

Affected product model name, firmware version and serial No. are the followings.

Series	Model name	Version	
MELSEC	iQ-R Series	R12CCPU-V	Firmware versions "16" and prior
	Q Series	Q03UDECPU, Q04/06/10/13/20/26/50/100UDEHCPU	The first 5 digits of serial No. "24061"and prior
		Q03/04/06/13/26UDVCPU	The first 5 digits of serial No. "24051"and prior
		Q04/06/13/26UDPVCPU	The first 5 digits of serial No. "24051"and prior
		Q12DCCPU-V, Q24DHCCPU-V(G), Q24/26DHCCPU-LS	The first 5 digits of serial No. "25061"and prior
L Series	L02/06/26CPU(-P), L26CPU(-P)BT	The first 5 digits of serial No. "24051"and prior	
MELIPC Series	MI5122-VW	Firmware versions "05" and prior	

Please refer to the following user's manual for how to check firmware version and serial No..

- MELSEC iQ-R Module Configuration Manual "Appendix 1 Checking Production Information and Firmware Version"
- QCPU User's Manual (Hardware Design, Maintenance and Inspection) "Appendix 5 Checking Serial Number and Function Version"
- MELSEC-L CPU Module User's Manual (Hardware Design, Maintenance and Inspection) "Appendix 5 Checking Serial Number and Function Version"
- MELIPC MI5000 Series User's Manual (Startup) "Appendix 17 Checking Production Information and Firmware Version"

Description

Denial of Service(DoS) vulnerability due to Improper Resource Locking (CWE-413²) exists in MELSEC iQ-R/Q/L series CPU module and MELIPC series.

Impact

A malicious attacker may cause a DoS condition in Ethernet communications by sending a specially crafted packet (CVE-2022-24946). A system reset of the products is required for recovery.

Countermeasures for Customers

<Customers using the affected models of MELSEC iQ-R Series firmware versions "08" and prior>

Take the following Mitigations / Workarounds.

We have released the fixed version as shown below, but updating the product to the fixed version is not available.

<Customers using the affected models of MELSEC iQ-R Series firmware versions "09" or later>

Download a fixed firmware update file from the following site and update the firmware.

<https://www.mitsubishielectric.com/fa/download/index.html>

Please refer to the following product manual for how to update firmware.

- MELSEC iQ-R Module Configuration Manual "Appendix 2 Firmware Update Function"

¹ <https://www.first.org/cvss/v3.1/specification-document>

² <https://cwe.mitre.org/data/definitions/413.html>

<Customers using the affected models of MELSEC Q Series>

Take the following Mitigations / Workarounds.

We have released the fixed version as shown below, but updating the product to the fixed version is not available.

Please consider migrating to MELSEC iQ-R Series.

<Customers using the affected models of MELSEC L Series>

Take the following Mitigations / Workarounds.

We have released the fixed version as shown below, but updating the product to the fixed version is not available.

Please consider migrating to MELSEC iQ-R Series.

<Customers using the affected models of MELIPC Series>

Take the following Mitigations / Workarounds.

We have released the fixed version as shown below, but updating the product to the fixed version is not available.

Countermeasures for Products

The following modules have been fixed.

Series		Model name	Version
MELSEC	iQ-R Series	R12CCPU-V	Firmware versions "17" or later
	Q Series	Q03UDECPU, Q04/06/10/13/20/26/50/100UDEHCPU	The first 5 digits of serial No. "24062" or later
		Q03/04/06/13/26UDVCPU	The first 5 digits of serial No. "24052" or later
		Q04/06/13/26UDPVCPU	The first 5 digits of serial No. "24052" or later
		Q12DCCPU-V, Q24DHCCPU-V(G), Q24/26DHCCPU-LS	The first 5 digits of serial No. "25062" or later
L Series	L02/06/26CPU(-P), L26CPU(-P)BT	The first 5 digits of serial No. "24052" or later	
MELIPC Series		MI5122-VW	Firmware versions "06" or later

Mitigations / Workarounds

Mitsubishi Electric recommends that customers take the following mitigation measures to minimize the risk of exploiting the vulnerability:

- Use a firewall or virtual private network (VPN), etc. to prevent unauthorized access when Internet access is required.
- Use within a LAN and block access from untrusted networks and hosts through firewalls.

Contact information

Please contact your local Mitsubishi Electric representative.

< Inquiries | MITSUBISHI ELECTRIC FA >

<https://www.mitsubishielectric.com/fa/support/index.html>

Update history

May 30, 2024

“Countermeasures” divided into “Countermeasures for Customers” and “Countermeasures for Products”.

Revised description regarding “Countermeasures for Customers”.

July 27, 2023

Added modules(Q12DCCPU-V, Q24DHCCPU-V (G), Q24/26DHCCPU-LS) that have been fixed to “Countermeasures”.

August 16, 2022

The title has been changed due to the addition of affected products.

Added modules(R12CCPU-V, Q12DCCPU-V, Q24DHCCPU-V (G), Q24/26DHCCPU-LS, MI5122-VW) to “Affected products”.

Added modules(R12CCPU-V, Q03UDECPU, Q04/06/10/13/20/26/50/100UDEHCPU, MI5122-VW) that have been fixed to “Countermeasures”.