

Multiple vulnerabilities in Wireless Communication Standards IEEE 802.11 (Frag Attacks)

Release date: September 2, 2021

Last update date: May 10, 2022

Mitsubishi Electric Corporation

■ Overview

There are multiple vulnerabilities due to design flaws in the frame fragmentation functionality and the frame aggregation functionality in Wireless Communication Standards IEEE 802.11. These vulnerabilities could allow an attacker to steal communication contents or inject unauthorized packets. The following are the product names affected by these vulnerabilities, please take workarounds.

■ CVSS

[A] CVE-2020-24586: CVSS:3.1/AV:A/AC:L/PR:N/UI:R/S:U/C:L/I:N/A:N Base Score:3.5
[B] CVE-2020-24587: CVSS:3.1/AV:A/AC:H/PR:N/UI:R/S:U/C:L/I:N/A:N Base Score:2.6
[C] CVE-2020-24588: CVSS:3.1/AV:A/AC:L/PR:N/UI:R/S:U/C:N/I:L/A:N Base Score:3.5
[D] CVE-2020-26139: CVSS:3.1/AV:A/AC:H/PR:N/UI:N/S:U/C:N/I:H/A:N Base Score:5.3
[E] CVE-2020-26140: CVSS:3.1/AV:A/AC:L/PR:N/UI:N/S:U/C:N/I:H/A:N Base Score:6.5
[F] CVE-2020-26142: CVSS:3.1/AV:N/AC:L/PR:N/UI:N/S:U/C:N/I:H/A:N Base Score:7.5
[G] CVE-2020-26143: CVSS:3.1/AV:A/AC:L/PR:N/UI:N/S:U/C:N/I:H/A:N Base Score:6.5
[H] CVE-2020-26144: CVSS:3.1/AV:A/AC:L/PR:N/UI:N/S:U/C:N/I:H/A:N Base Score:6.5
[I] CVE-2020-26145: CVSS:3.1/AV:A/AC:L/PR:N/UI:N/S:U/C:N/I:H/A:N Base Score:6.5
[J] CVE-2020-26146: CVSS:3.1/AV:A/AC:H/PR:N/UI:N/S:U/C:N/I:H/A:N Base Score:5.3
[K] CVE-2020-26147: CVSS:3.1/AV:A/AC:H/PR:N/UI:R/S:U/C:L/I:H/A:N Base Score:5.4

■ Description

12 vulnerabilities have been found in Wireless Communication Standards IEEE 802.11. These vulnerabilities are called "FragAttacks" and could allow an attacker to steal communication contents or inject unauthorized packets. Please check the following 11 ([A] - [K]) of the 12 vulnerabilities that may affect each product in "Affected products, countermeasures, and mitigations or workarounds".

- [A] Fragment cache attack (not clearing fragments from memory when (re)connecting to a network) (CVE-2020-24586) (CWE-212)
- [B] Mixed key attack (reassembling fragments encrypted under different keys) (CVE-2020-24587) (CWE-326)
- [C] Aggregation attack (accepting non-SPP A-MSDU frames) (CVE-2020-24588) (CWE-306)
- [D] Forwarding EAPOL frames even though the sender is not yet authenticated (should only affect APs) (CVE-2020-26139) (CWE-287)
- [E] Accepting plaintext data frames in a protected network (CVE-2020-26140) (CWE-74)
- [F] Processing fragmented frames as full frames (CVE-2020-26142) (CWE-74)
- [G] Accepting fragmented plaintext data frames in a protected network (CVE-2020-26143) (CWE-20)
- [H] Accepting plaintext A-MSDU frames that start with an RFC1042 header with EtherType EAPOL (in an encrypted network) (CVE-2020-26144) (CWE-20)
- [I] Accepting plaintext broadcast fragments as full frames (in an encrypted network) (CVE-2020-26145) (CWE-20)
- [J] Reassembling encrypted fragments with non-consecutive packet numbers (CVE-2020-26146) (CWE-20)
- [K] Reassembling mixed encrypted/plaintext fragments (CVE-2020-26147) (CWE-74)

■ Impact

These 11 vulnerabilities could allow an attacker to steal communication contents or inject unauthorized packets during frame aggregation or frame fragmentation.

■ Affected products, countermeasures, and mitigations or workarounds

[1] [Wi-Fi Interfaces]

Model	Countermeasures and Mitigations/Workarounds
MAC-557IF-E MAC-558IF-E MAC-559IF-E PAC-WF010-E PAC-WHS01WF-E The above models of all versions. May be affected by [C] or[E]	<Countermeasures> Please carry out mitigation or workaround below. <Mitigations/Workarounds> 1.Check if the router settings are as follows. 1-1. Set encryption key of wireless LAN which can hardly be identified. If key is changed from initial setting, avoid consecutive numbers and guessable MAC address, and combine letters and numbers. 1-2. Do not use WEP encryption algorithm or Open authentication. 1-3. If you change the router settings, hide its presence on the internet in order to make it difficult for unauthorized access. (e.g. Set to not respond to PING request) 1-4. Set password for the router's Management portal, which is difficult to be identified. 2.Check the following when using a computer or tablet, etc. at home. 2-1. Update Antivirus software to the latest version. 2-2. Do not open or access suspicious attachment file or linked URL.

*Contact information

Please contact your local Mitsubishi Electric representative.

<Inquiries>

<https://www.mitsubishielectric.com/en/contact/room-air-conditioners.page>

[2] [Wi-Fi Interfaces and Air Conditioning]

Model	Countermeasures and Mitigations/Workarounds
<u>Wi-Fi Interfaces:</u> MAC-567IF-E MAC-568IF-E S-MAC-905IF S-MAC-906IF <u>Air Conditioning:</u> MSZ-FT20/25VFK MSZ-FX20/25VFK MSZ-GZT09/12/18VAK MSZ-GZT09/12/18VAK-1 MSZ-ZT09/12/18VAK MSZ-ZT09/12/18VAK-1 MSZ-AP25/35/42/50VGK-E6 MSZ-AP60/71VGK-E1 MSZ-AP60/71VGK-ER1 MSZ-AP60/71VGK-ET1 MSZ-LN18/25/35/50/60VGW(V)(R)(B)-E1 MSZ-LN18/25/35/50/60VG2W(V)(R)(B)-E1 MSZ-LN25/35/50/60VGW(V)(R)(B)-ER1 MSZ-LN25/35/50/60VG2W(V)(R)(B)-ER1 MSZ-LN18VG2W-ER1 MSZ-LN25/35/50/60VG2W(V)(R)(B)-ET1 MSZ-LN25/35/50VG2W(V)(R)(B)-EN1 MSZ-AP22/25/35/42/50/60/71/80VGKD-A1 MSZ-AP22/25/35/42/50/60/71/80VGKD-A2 MSZ-LN25/35/50/60VGV(R)(B)-A1 MSZ-LN25/35/50/60VG2V(R)(B)-A1 The above models of all versions. May be affected by [B],[C],[F],[H],[I],[J].	<Countermeasures> Please carry out mitigation or workaround below. <Mitigations/Workarounds> 1.Check if the router settings are as follows. 1-1. Set encryption key of wireless LAN which can hardly be identified. If key is changed from initial setting, avoid consecutive numbers and guessable MAC address, and combine letters and numbers. 1-2. Do not use WEP encryption algorithm or Open authentication. 1-3. If you change the router settings, hide its presence on the internet in order to make it difficult for unauthorized access. (e.g. Set to not respond to PING request) 1-4. Set password for the router's Management portal, which is difficult to be identified. 2.Check the following when using a computer or tablet, etc. at home. 2-1. Update Antivirus software to the latest version. 2-2. Do not open or access suspicious attachment file or linked URL.

*Contact information

Please contact your local Mitsubishi Electric representative.

<Inquiries>

<https://www.mitsubishielectric.com/en/contact/room-air-conditioners.page>

[3] [Wi-Fi Interfaces and Air Conditioning]

Model	Countermeasures and Mitigations/Workarounds
<p><u>Wi-Fi Interface:</u> S-MAC-002IF</p> <p><u>Air Conditioning:</u> MFZ-GXT50/60/73VFK MFZ-XT50/60/73VFK MSZ-GZY09/12/18VFK MSZ-KY09/12/18VFK MSZ-WX18/20/25VFK MSZ-ZY09/12/18VFK MSZ-AP15/20/25/35/42/50VGK-E1 MSZ-AP15/20/25/35/42/50VGK-ER1 MSZ-AP15/20/25/35/42/50VGK-ET1 MSZ-AP25/35/42/50VGK-EN1 MSZ-AP15/20/25/35/42/50/60/71VGK-E2 MSZ-AP15/20/25/35/42/50/60/71VGK-ER2 MSZ-AP15/20/25/35/42/50/60/71VGK-ET2 MSZ-AP25/35/42/50VGK-EN2 MSZ-AP25/35/42/50/60/71VGK-E3 MSZ-AP25/35/42/50/60/71VGK-ER3 MSZ-AP25/35/42/50/60/71VGK-ET3 MSZ-AP25/35/42/50VGK-EN3 MSZ-AP25/35/42/50VGK-E7 MSZ-AP25/35/42/50VGK-E8 MSZ-BT20/25/35/50VGK-E1 MSZ-BT20/25/35/50VGK-E2 MSZ-BT20/25/35/50VGK-ET1 MSZ-EF18/22/25/35/42/50VGKW(S)(B)-E1 MSZ-EF22/25/35/42/50VGKW(S)(B)-ER1 MSZ-EF25VGKB-ET1 MSZ-FT25/35/50VGK-E1 MSZ-FT25/35/50VGK-ET1 MSZ-FT25/35/50VGK-SC1 MSZ-LN18/25/35/50/60VG2W(B)(R)(V)-E2 MSZ-LN25/35/50/60VG2W(B)(R)(V)-ER2 MSZ-LN25/35/50/60VG2W(B)(R)(V)-ET2 MSZ-LN25/35/50VG2W(B)(R)(V)-EN2 MSZ-RW25/35/50VG-E1 MSZ-RW25/35/50VG-ER1 MSZ-RW25/35/50VG-ET1 MSZ-RW25/35/50VG-SC1 MSZ-EF22/25/35/42/50VGKW(S)(B)-A1 MSZ-LN25/35/50/60VG2V(R)(B)-A2</p> <p>The above models of version 3300 or less. “Version” is printed on Wi-Fi interface.</p> <p>May be affected by [A],[B],[C],[D],[E],[G],[H],[I],[J],[K].</p>	<p><Countermeasures> Please carry out mitigation or workaround below.</p> <p><Mitigations/Workarounds> 1.Check if the router settings are as follows. 1-1. Set encryption key of wireless LAN which can hardly be identified. If key is changed from initial setting, avoid consecutive numbers and guessable MAC address, and combine letters and numbers. 1-2. Do not use WEP encryption algorithm or Open authentication. 1-3. If you change the router settings, hide its presence on the internet in order to make it difficult for unauthorized access. (e.g. Set to not respond to PING request) 1-4. Set password for the router’s Management portal, which is difficult to be identified.</p> <p>2.Check the following when using a computer or tablet, etc. at home. 2-1. Update Antivirus software to the latest version. 2-2. Do not open or access suspicious attachment file or linked URL.</p>

*Contact information

Please contact your local Mitsubishi Electric representative.

<Inquiries>

<https://www.mitsubishielectric.com/en/contact/room-air-conditioners.page>

[4] [Wireless LAN communication unit for GOT]

Model	Countermeasures and Mitigations/Workarounds
<p>GT25-WLAN (In the GOT2000 series GT25 or GT27 models)</p> <p>System applications(extended function) “Wireless LAN” in the above models version 01.39.000 and earlier.</p> <p>May be affected by [A],[B],[C],[E],[G],[H],[J].</p>	<p><Countermeasures></p> <p>For customers who use the affected products and versions, please update to the fixed versions by following the steps below.</p> <p>How to check the versions in use For how to check the versions in use, please refer to the following manual.</p> <p>GOT2000 Series User’s Manual (Utility) (SH-081195ENG) “6.9 Package Data Management” – “Property operation” The latest version of manual is available from MITSUBISHI ELECTRIC FA Global Website (https://www.mitsubishielectric.com/fa).</p> <p>Fixed versions System applications (extended function) “Wireless LAN” version: 01.45.000 or later (Fixed system applications (extended function) “Wireless LAN” is included in GT Designer3 Version1(GOT2000) Ver.1.275M or later) It does not include countermeasures for the CVE-2020-26146 (Description [J]). Please carry out mitigation or workaround below.</p> <p>Update procedure</p> <ol style="list-style-type: none"> Download the fixed version of MELSOFT GT Designer3 (2000) and install it on your personal computer. Please contact your local Mitsubishi Electric representative about MELSOFT GT Designer3 (2000). Start the MELSOFT GT Designer3 (2000) and open the project data used in affected products. Select [Write to GOT] from [Communication] menu to write the required package data to the GOT. * Please refer to “4. COMMUNICATING WITH GOT” in the GT Designer3 (GOT2000) Screen Design Manual (SH-081220ENG). After writing the required package data to the GOT, refer to the “How to check the versions in use” and check the fixed versions. <p><Mitigations/Workarounds></p> <ol style="list-style-type: none"> When using the wireless LAN communication unit as an access point, check if the wireless LAN communication unit settings are as follows. <ol style="list-style-type: none"> For the passphrase used for wireless LAN, avoid settings that can be guessed from the consecutive numbers and MAC address, and set an unpredictable passphrase combining letters and numbers. Use WPA or WPA2 as the security authentication method for wireless LAN. Use the IP filter function*1 to restrict the accessible IP addresses. *1: GT Designer3 (GOT2000) Screen Design Manual(SH-081220ENG). “5.4.3 Setting the IP filter” When using the wireless LAN communication unit as a station, check if the router settings are as follows. <ol style="list-style-type: none"> For the passphrase used for wireless LAN, avoid settings that can be guessed from the consecutive numbers and MAC address, and set an unpredictable passphrase combining letters and numbers. Use WPA or WPA2 as the security authentication method for wireless LAN. If you change the router settings, hide its presence on the internet in order to make it difficult for unauthorized access. (e.g. Set to not respond to PING request) Set password for the router’s Management portal, which is difficult to be identified. Check the following when using a computer or tablet, etc. on the same network. <ol style="list-style-type: none"> Update Antivirus software to the latest version. Do not open or access suspicious attachment file or linked URL.

***Contact information**

Please contact your local Mitsubishi Electric representative.

<Inquiries | MITSUBISHI ELECTRIC FA>

<https://www.mitsubishielectric.com/fa/support/index.html>

■ Update history

May 10, 2022

Add fixed products as below

[4] [Wireless LAN communication unit for GOT]

March 22, 2022

Added "[4] [Wireless LAN communication unit for GOT]" to affected products.