

# Denial-of-Service (DoS) Vulnerability and Arbitrary Command Execution Vulnerability due to OpenSSL Vulnerabilities in Multiple FA Products

Release date: August 2, 2022  
Last update date: January 31, 2023  
Mitsubishi Electric Corporation

## ■ Overview

Denial-of-service(DoS) vulnerability and arbitrary command execution vulnerability due to OpenSSL vulnerabilities exist in multiple Mitsubishi Electric FA Products. An attacker could cause denial-of-service (DoS) condition or execute arbitrary malicious commands by sending a specially crafted packet. (CVE-2022-0778, CVE-2022-1292)

## ■ CVSS

CVE-2022-0778 CVSS:3.1/AV:N/AC:L/PR:N/UI:N/S:U/C:N/I:N/A:H Base Score:7.5  
CVE-2022-1292 CVSS:3.1/AV:N/AC:L/PR:N/UI:N/S:U/C:H/I:H/A:H Base Score:9.8

## ■ Affected products

Affected products and versions are below.

No.	Product Name	Model Name	Affected software/firmware version	Applicable CVE ID
1	GOT2000 compatible HMI software	GT SoftGOT2000	1.275M	CVE-2022-0778 CVE-2022-1292
2	CC-Link IE TSN Industrial Managed Switch	NZ2MHG-TSNT8F2 NZ2MHG-TSNT4	"03" and prior	CVE-2022-0778
3	MELSEC iQ-R Series OPC UA Server Module	RD81OPC96	"08" and prior	CVE-2022-0778

[How to check the version in use]

1. GOT2000 compatible HMI software (Model Name: GT SoftGOT2000)
  - (1) Run GT SoftGOT2000.
  - (2) From the Help menu, select [About GT SoftGOT2000...].
  - (3) Check the version on "About GT SoftGOT2000" window (see Figure 1).




Figure 1 GT SoftGOT2000 version information view

2. CC-Link IE TSN Industrial Managed Switch (Model Name: NZ2MHG-TSNT8F2, NZ2MHG-TSNT4)

- (1) After you log into NZ2MHG-TSNT8F2 or NZ2MHG-TSNT4 with the web interface, [Device Summary] screen is displayed.
- (2) Confirm the first 2 digits of Firmware Version on Model Information displayed in [Device Summary] screen.(see Figure 2)  
ex) When “02 Build xxxx” is displayed, its firmware version is “02”.




Figure 2 NZ2MHG-TSNT8F2 Model Information view

3. MELSEC iQ-R Series OPC UA Server Module (Model Name: RD81OPC96)

- (1) Run engineering software(GX Works3, CW Configurator) and connect to PLC.
- (2) Select [Diagnostics] -> [System Monitor] -> [Product Information List].
- (3) [Product Information List] will be displayed and confirm the Firmware Version.(see Figure 3).




Figure 3 Engineering Software Product Information List view

■ Description

Denial-of-service(DoS) vulnerability (CVE-2022-0778) and arbitrary command execution vulnerability (CVE-2022-1292) exist in multiple Mitsubishi Electric FA Products due to the following vulnerabilities in OpenSSL.

- CVE-2022-0778: Loop with Unreachable Exit Condition ('Infinite Loop') (CWE-835)
- CVE-2022-1292: Improper Neutralization of Special Elements used in an OS Command ('OS Command Injection') (CWE-78)

■ Impact

The vulnerabilities could allow an attacker to cause a denial-of-service (DoS) condition or execute arbitrary malicious commands by sending specially crafted packets.

## ■ Countermeasures

Please update to the fixed versions by following the steps below.

### [Fixed versions]

No.	Product Name	Model Name	Fixed software/firmware version
1	GOT2000 compatible HMI software	GT SoftGOT2000	1.280S or later
2	CC-Link IE TSN Industrial Managed Switch	NZ2MHG-TSNT8F2 NZ2MHG-TSNT4	"04" or later
3	MELSEC iQ-R Series OPC UA Server Module	RD81OPC96	"09" or later

### [Update steps]

#### 1. GOT2000 compatible HMI software (Model Name: GT SoftGOT2000)

- (1) Please contact your local Mitsubishi Electric representative to obtain the fixed version of GT SoftGOT2000 and install it on a personal computer. For detailed installation procedures, please refer to "GT SoftGOT2000 Version1 Operation Manual (SH-081201ENG)".
- (2) Refer to the <How to check the version in use> to check that the software has been updated to the fixed versions.

#### 2. CC-Link IE TSN Industrial Managed Switch (Model Name: NZ2MHG-TSNT8F2, NZ2MHG-TSNT4)

- (1) Please contact your local Mitsubishi Electric representative to obtain the fixed firmware version of CC-Link IE TSN Industrial Managed Switch.
- (2) After you log into NZ2MHG-TSNT8F2 or NZ2MHG-TSNT4 with the web interface, please update the firmware to the above mentioned fixed firmware version file by the function of [System] -> [System Management] -> [Firmware Upgrade] from Function menu.  
For the detailed procedures, please refer to "CC-Link IE TSN Industrial Managed Switch User's Manual (SH-082449ENG)".
- (3) Refer to the <How to check the version in use> to check that the firmware has been updated to the fixed version.

#### 3. MELSEC iQ-R series OPC UA Server Module (Model Name: RD81OPC96)

- (1) Please contact your local Mitsubishi Electric representative to obtain the fixed firmware version of OPC UA Server Module.
- (2) Please update the firmware of OPC UA Server Module using an SD memory card.  
For the detailed procedures, please refer to "MELSEC iQ-R Module Configuration Manual (SH-081262ENG)".
- (3) Refer to the <How to check the version in use> to check that the firmware has been updated to the fixed version.

## ■ Mitigations

Mitsubishi Electric recommends that customers take the following mitigations to minimize the risk of exploiting these vulnerabilities:

- When Internet access is required, use a virtual private network (VPN) or other means to prevent unauthorized access.
- Use the products within a LAN and block access from untrusted networks and hosts.
- Restrict physical access to your computer with the products installed and network equipment on the same network.

Also, recommends to take the following mitigations according to the affected products.

#### 1. GOT2000 compatible HMI software (Model Name: GT SoftGOT2000)

- Update the OPC UA server to the latest version.
- Install antivirus software on your computer with the products installed.

#### 2. CC-Link IE TSN Industrial Managed Switch (Model Name: NZ2MHG-TSNT8F2, NZ2MHG-TSNT4)

- After you log into NZ2MHG-TSNT8F2 or NZ2MHG-TSNT4 with the web interface, change user name and password from default setting at [Account Management] displayed on the function menu. Also, set the proper access permissions depending on the users.

#### 3. MELSEC iQ-R Series OPC UA Server Module (Model Name: RD81OPC96)

- Update the OPC UA Client to latest version.
- Use legitimate certificate(certificcate that can be determined not to be fabricated) on OPC UA Client side.

■ Contact information

Please contact your local Mitsubishi Electric representative.

< Inquiries | MITSUBISHI ELECTRIC FA >

<https://www.mitsubishielectric.com/fa/support/index.html>

■ Update history

January 31, 2023

Added the fixed firmware version and update steps of RD81OPC96 to “Countermeasures”.

November 1, 2022

Added the fixed firmware version and update steps of NZ2MHG-TSNT8F2 and NZ2MHG-TSNT4 to “Countermeasures”.

August 30, 2022

Added NZ2MHG-TSNT4 to “Affected products”, “Countermeasures” and “Mitigations”.

August 18, 2022

Added NZ2MHG-TSNT8F2 and RD81OPC96 to “Affected products”, “Countermeasures” and “Mitigations”.