

Denial of Service (DoS) and Malicious Code Execution Vulnerability in MITSUBISHI CNC Series

Release date: July 27, 2023
Last Update date: January 30, 2024
Mitsubishi Electric Corporation

Overview

Denial of Service (DoS) and Malicious Code Execution vulnerability exists in MITSUBISHI CNC series. A malicious remote attacker may cause DoS condition and execute malicious code on the product by sending specially crafted packets. (CVE-2023-3346)
The product models and system versions affected by this vulnerability are listed below.

CVSS¹

CVE-2023-3346 CVSS:3.1/AV:N/AC:L/PR:N/UI:N/S:U/C:H/I:H/A:H Base Score:9.8

Affected products

The following products, System Number and Versions are affected:

Series	Product	System Number (**=Version)	Version
M800V/M80V Series	M800VW	BND-2051W000-**	A8 and prior
	M800VS	BND-2052W000-**	
	M80V	BND-2053W000-**	
	M80VW	BND-2054W000-**	
M800/M80/E80 Series	M800W	BND-2005W000-**	FB and prior
	M800S	BND-2006W000-**	
	M80	BND-2007W000-**	
	M80W	BND-2008W000-**	
	E80	BND-2009W000-**	
C80	C80	BND-2036W000-**	BF and prior
M700V/M70V/E70 Series	M750VW	BND-1015W002-**	LF and prior
	M730VW/M720VW	BND-1015W000-**	
	M750VS	BND-1012W002-**	
	M730VS/M720VS	BND-1012W000-**	
	M70V	BND-1018W000-**	
	E70	BND-1022W000-**	
IoT Unit	Remote Service Gateway Unit	BND-2041W001-**	AD and prior
	Data Acquisition Unit	BND-2041W002-**	All versions

For M800V/M80V, M800/M80/E80, C80, and M700V/M70V/E70 Series, please check "System Number" by following steps.

- 1) Display "Diagnostics" screen on the display unit of CNC, select "Config" menu and display "S/W Configuration" screen.
- 2) Confirm "System Number" displayed in "NCMAIN1" item on "S/W Configuration" screen.

For IoT Unit, open the web configuration tool from a web browser on your PC and check the "S/W Version" displayed on the tool's screen.

Description

Denial of service (DoS) and malicious code execution vulnerability exists in the product due to "Buffer Copy without Checking Size of Input ('Classic Buffer Overflow')"(CWE-120)².

Impact

A malicious remote attacker may cause DoS condition and execute malicious code on the product by sending specially crafted packets. In addition, system reset is required for recovery.

¹ <https://www.first.org/cvss/v3.1/specification-document>

² <https://cwe.mitre.org/data/definitions/120.html>

Countermeasures

The series, product names, system numbers and versions in which the vulnerability has been fixed are as follows.

<Series, system number and version>

Series	Product	System Number (**=Version)	Version
M800V/M80V Series	M800VW	BND-2051W000-**	A9 or later
	M800VS	BND-2052W000-**	
	M80V	BND-2053W000-**	
	M80VW	BND-2054W000-**	
M800/M80/E80 Series	M800W	BND-2005W000-**	FC or later
	M800S	BND-2006W000-**	
	M80	BND-2007W000-**	
	M80W	BND-2008W000-**	
	E80	BND-2009W000-**	
C80	C80	BND-2036W000-**	BG or later
M700V/M70V/E70 Series	M750VW	BND-1015W002-**	LG or later
	M730VW/M720VW	BND-1015W000-**	
	M750VS	BND-1012W002-**	
	M730VS/M720VS	BND-1012W000-**	
	M70V	BND-1018W000-**	
	E70	BND-1022W000-**	
IoT Unit	Remote Service Gateway Unit	BND-2041W001-**	AE or later

<How to apply fixed version>

Please contact your local Mitsubishi Electric representative for information on how to apply the fixed version.

Mitigations / Workarounds

For customers who cannot update their systems immediately, Mitsubishi Electric recommends taking the mitigations listed below to minimize the risk of exploitation of this vulnerability.

- Use a firewall or virtual private network (VPN), etc. to prevent unauthorized access when Internet access is required.
- Install anti-virus software on your PC that can access the product.
- Use within a LAN and block access from untrusted networks and hosts through firewalls.
- Restrict physical access to the affected product and the LAN to which the product is connected.

Acknowledgement

Mitsubishi Electric would like to thank 01dGu0 of ZHEJIANG QIAN INFORMATION&TECHNOLOGY CO., LTD. who reported this vulnerability.

Contact information

Please contact your local Mitsubishi Electric representative.

<Inquiries | MITSUBISHI ELECTRIC FA>

<https://www.mitsubishielectric.com/fa/support/index.html>

Update history

January 30, 2024

Added products that have been fixed to "Countermeasures".
C80

December 5, 2023

Added products that have been fixed to "Countermeasures".
Remote Service Gateway Unit

November 21, 2023

Added products that have been fixed to "Countermeasures".
M800VW, M800VS, M80V, M80VW, M750VW, M730VW/M720VW, M750VS, M730VS/M720VS, M70V, E70

October 31, 2023

Corrected Product and System Number of "Affected products".
Corrected System Number of M730VS
Deleted M750VS 15-type and M730VS/M720VS 15-type
Added products that have been fixed to "Countermeasures".
M800W, M800S, M80, M80W, E80

August 3, 2023

Corrected Product and System Number of "Affected products".
M730VW/M720VW, M720VS
Added Product and System Number that have been fixed to "Affected products".
M750VW, M750VS, M730VS, M750VS 15-type, M730VS/M720VS 15-type