

TECHNICAL BULLETIN

[Issue No.] FA-A-0117

[Page] 1/2

[Title] Compliance with the new Radio Waves Act (South Korea)

[Date of Issue] August 2011

[Relevant Models] MELSEC-Q/L/QS/WS/AnS, CC-Link, and CC-Link/LT series, PC interface boards*

*: For relevant models, please go to MELFANSweb website:
<http://www.MitsubishiElectric.co.jp/melfansweb/english/>

Thank you for your continued support of Mitsubishi programmable controllers (MELSEC-Q/L/QS/WS/AnS, CC-Link, and CC-Link/LT series) and PC interface boards.

Article 58-2 of the new Radio Waves Act (South Korea) came into effect. Our programmable controllers and PC interface boards must meet the requirements of the new Act. This bulletin informs users of the changes we made to our products to comply with the Act. There is no impact on the product functions and performance due to these changes.

1. Reason for changes

To comply with Article 58-2 of the new Radio Waves Act (South Korea).

2. Relevant models

Products of the following series are targeted. (Some models are exempt.)

- MELSEC-Q series
- MELSEC-L series
- MELSEC-QS series
- MELSEC-WS series
- MELSEC-AnS series
- CC-Link series
- CC-Link/LT series
- PC interface boards

3. Change details

(1) Placing the KC mark and certification number on both product (rating plate) and package




Figure 1 Example of a new rating plate

TECHNICAL BULLETIN

[Issue No.] FA-A-0117

[Page] 2/2

[Title] Compliance with the new Radio Waves Act (South Korea)

[Date of Issue] August 2011

[Relevant Models] MELSEC-Q/L/QS/WS/AnS, CC-Link, and CC-Link/LT series, PC interface boards*

*: For relevant models, please go to MELFANSweb website:
<http://www.MitsubishiElectric.co.jp/melfansweb/english/>



Figure 2 Example of a new package

(2) Providing handling precautions in Korean

Precautions for handling products have been available on the following website since August 1, 2011.

• Mitsubishi Electric Automation Korea Co.,Ltd.: <http://www.mitsubishi-automation.co.kr/>

Until the end of July, the following precautionary note was provided with each product.




Figure 3 Precautionary note in Korean

4. Date of change

The changes have been made to products since June 1, 2011.

Note that some products before change may be distributed in the market around this date.

5. Others

To export products to South Korea, the products must have the KC mark. For details, please consult your local Mitsubishi representative.