

TECHNICAL BULLETIN

[Issue No.] T12-0006

[Page] 1/1

[Title] Measures Regarding Year 2000 Problem for
Software Package of Special Function Modules

[Date of Issue] Nov. '98

[Relevant Models] Software Package for AD71,AD75 and AD57

Thank you for your continued patronage of the Mitsubishi general-purpose PLC MELSEC-A Series.

The year 2000 problem includes recognizing the years before 1999 and after 2000, and compensating the date in leap years.

This will be handled as follows for the software package for the AD71, AD75 and AD57.

Whereas

[Details]

With the A7PHP and A7HGP that operate the SW*-AD71P, SW*-AD75P and SW*-AD57P software packages, if the system is reset or the power turned ON after the year 2000, the date will be changed to 1980. Thus, the date must be reset. (Refer to T50-0006)

However, with the above software packages, functions such as file date control, etc., using the clock function built into the A7PHP and A7HGP are not supported, so measures are not required.



MITSUBISHI ELECTRIC CORPORATION

HEAD OFFICE MITSUBISHI DENKI BLDG. MARUNOUCHI. TOKYO 100-0005. TELEX J24532 CABLE MELCO TOKYO