

## Changes in the Rating Plate of MELIPC MI2000 Series for CCC Certification

■Date of Issue

June 2024

■Relevant Models

MI2012-W, MI2012-W-CL

Thank you for your continued support of Mitsubishi Electric industrial PC, MELIPC series.

We are informing you that the Chinese precautions on the rating plate of MELIPC MI2000 will be changed.

There is no impact on the general specifications, performance specifications, and functions of the industrial PC due to the changes.

### 1 RELEVANT MODELS

Series	Model
MELIPC MI2000	MI2012-W
	MI2012-W-CL

### 2 REASON FOR THE CHANGES

With the renewal of the CCC certification, it is required to change the precautions on the rating plate.

**Point**

CCC is an abbreviation for China Compulsory Certification.

This is a certification system in China for the purpose of protecting consumers and ensuring safety in China.

It is related to export, distribution, and sale of products to China.

### 3 DETAILS ON THE CHANGES

The Chinese precautions on the rating plate will be changed as shown below.

Before change	After change
<p>警告使用者 這是甲類的測試產品，在居住的環境中使用時，可能會造成射頻干擾，在這種情況下，使用者會被要求採取某些適當的對策。</p> <p>声明 此为A级产品，在生活环境中，该产品可能会造成无线电干扰，在这种情况下，可能需要用户对其干扰采取切实可行的措施。</p> <p>注意 产品避免碰撞，请勿自行拆卸机壳。机台内部无客户可自行处理部分，如有问题请洽寻专业人员。</p>	<p>警告 為避免電磁干擾，本產品不應安裝或使用於住宅環境。</p> <p>警告 在居住環境中，運行此設備可能會造成無線電干擾。</p> <p>注意 產品避免撞擊。勿自行拆卸機殼。機台內部無客戶可自行處理的部分。若有問題請洽詢專業人員。</p>

## 4 CHANGEOVER PERIOD

---

The changes will take place one by one for products manufactured in and after June 2024.

Depending on stock status, both the old and new products may be distributed in the market around that time.

### Precautions

The CCC certification (GB9254.1) obtained by the applicable products before the changes will expire on July 31st, 2024.

After August 1st, 2024, products before the changes cannot be exported to China.

### REVISIONS

Version	Date of issue	Revision
A	June 2024	First edition

### TRADEMARKS

The company names, system names and product names mentioned in this bulletin are either registered trademarks or trademarks of their respective companies.

In some cases, trademark symbols such as "™" or "®" are not specified in this bulletin.