

TECHNICAL BULLETIN

[Issue No.] T03-0010

[Page] 1/1

[Title] Notification of Error Correction on Description
of A1SJH/A1SH/A2SHCPU(S1) User's Manual

[Date of Issue] July, 1998

[Relevant Models] A1SJHCPU, A1SHCPU

Thank you for purchasing Mitsubishi general-purpose programmable controller MELSEC-A Series.

The user's manual for A1SJHCPU/A1SHCPU/A2SHCPU(S1) (IB-66779-C) contains the errors shown below.

In Chapter 4, The entries for A1SJHCPU and A1SHCPU in Table 4.1 (Actual number of I/O points / Standard) are incorrect

(ERROR VERSION)

Item \ Type	A1SJHCPU	A1SHCPU	A2SHCPU(S1)
Actual number of I/O points	512	512	A2SH:512 A2SH-S1:1024
Standard	UL/cUL		UL/cUL

(CORRECT VERSION)

Item \ Type	A1SJHCPU	A1SHCPU	A2SHCPU(S1)
Actual number of I/O points	256	256	A2SH:512 A2SH-S1:1024
Standard	UL/cUL	UL/cUL	UL/cUL